

BUMPER STICKER/DECAL & VINYL LETTERING APPLICATION

In order to have your decal adhere properly to the surface, please follow these simple directions.

- 1. Clean the surface of the area you will be placing your decal with alcohol or rapid tac. Clean thoroughly. Let it dry.**
- 2. Place the decal and position where desired (measure for accuracy).**
- 3. With a low tac masking tape, tape across the top of the decal (for larger graphics), creating a "hinge".**
- 4. Spray surface with a little rapid tac, to moisten.**
- 5. Carefully remove the backing of the decal, starting with the top corner.**
- 6. Use squeegee to smooth decal on surface.**